


AKI Setting (Optical Sensor/Mechanical shock)

1. Software setting:

Press ctrl+alt+shift+e, go into machine parameter

Select “Expand parameter”



Parameter item	Value	Unit	Range Of Value
Width of cut	<input checked="" type="checkbox"/>		
The cutting direction	From big to small		
Cutting back and forth	<input type="checkbox"/>		
The first knife 1	<input type="checkbox"/>		
The first knife 2	<input type="checkbox"/>		
The first knife 3	<input type="checkbox"/>		
The first knife 4	<input type="checkbox"/>		
Control mode	The level of single		
Effective control signal low	<input type="checkbox"/>		
Complete signal active low	<input type="checkbox"/>		
knife-set vibration speed	18.000	rev/min	0.000 ~ 4590.000
Knife-lift vibration speed	18.000	rev/min	0.000 ~ 4590.000
Sharpening vibration speed	18.000	rev/min	0.000 ~ 4590.000
Vacuum Pressure	-1.000	Kpa	-25.500 ~ -0.200
To keep the vacuum pressure	-1.000	Kpa	-25.500 ~ -0.200
Collecting material speed	0.600	m/s	0.000 ~ 50.000
Drilling 1 Speed	300.000	rev/min	0.000 ~ 6000.000
Drilling 2 Speed	30.000	rev/min	0.000 ~ 6000.000
Normal pressure value	4.000	Kpa	0.000 ~ 4000.000
Mane felt independence movemer	0.050	m/s	0.050 ~ 0.250
Linkage beam movement speed(o	0.050	m/s	0.020 ~ 0.150
Knife intelligent sensitivity	5	Level	
Knife Smart Range	15		
Massive suction models	YK		

BK3 Automatic knife initialization: Optronic Sensor (If your machine is mechanical AKI, you need select mechanical shock)

Whether on both sides of the knife: ×

Both sides of the knife: Unilateral knife.

Parameter Set

Expand Param

Parameter item	Value	Unit	Range Of Value
Router3 speed	1.000	kilo rev/min	1.000 ~ 60.000
Vibration blade start time	0.000	s	0.000 ~ 2.550
Rotate blade start time	0.000	s	0.000 ~ 2.550
Use Absolute Origin	<input type="checkbox"/>		
Drilling 2 Speed	30.000	rev/min	30.000 ~ 6000.000
Vacuum Pressure AD value when z	0.000		-128.000 ~ 127.000
Vacuum Pressure Ratio	0.000		0.000 ~ 2.550
Compressor Pressure AD value wh	0.000		-128.000 ~ 127.000
Compressor Pressure Ratio	0.000		0.000 ~ 2.550
FZ Auxiliary Plate Model	GLK		
Vacuum Pressure start time	0.000	s	0.000 ~ 25.500
FZ1 Board Warning Lights Flash	<input checked="" type="checkbox"/>		
The percentage of the upper limit	0.000		0.000 ~ 100.000
Automatic Knife Initialization	Optronic Sensor		
Grinding Compensation Angle	0.000	degrees	0.000 ~ 360.000
V-notch Compensation	0.000	mm	0.000 ~ 2.550
Grinding Indent	0.000	micrometer	0.000 ~ 255.000
Use PN Feeding Length	<input type="checkbox"/>		
After Over Window Wait Time	0.000	s	0.000 ~ 127.000
before Over Window Wait Time	0.000	s	0.000 ~ 127.000
Is PT3 rotate	<input type="checkbox"/>		
PT3 rotate speed	1.000	rev/s	0.000 ~ 255.000
Splint 1 High 1	0.000	mm	0.000 ~ 655.000
Splint 2 High 1	0.000	mm	0.000 ~ 655.000

Sure Cancel Exit(E)

The IO function redefines 1	Custom machine XK		
Both sides of the knife	Both sides of the knife(1 + 1 way)		
beam zone	Unilateral knife	m	2.000 ~ 500.0
Select Tracks	Both sides of the knife(2 + 2 way)		
Motor to track down	Do not track down		
A slant cruising altitude	<input type="checkbox"/>		
Enable tool changing speed	<input type="checkbox"/>		
Turn on automatic tool change	<input type="checkbox"/>		
Brush drop depth	0.000	mm	0.000 ~ 60.00
Cleaning plate brush fine tuning k	0.000	mm	0.000 ~ 6.00

2. Preparation

Make sure that every head can cut in same point ,no matter which head you select they always lower down in same position.

3. Set AKI coordinate


Open cutterserver, configuration → Automatic knife Initialization →

First Adjust Tool Point

Tips:

First adjust tool point: used for set first(right) AKI device coordinate.

For BK3 machine, only need set first adjust tool point.



Select “first adjust tool point”


Use keyboard to move the first cutting head toward to AKI device (right side)

Make sure the head center at the center of AKI device, if a cutting tool installed on the head ,when the head lower down the blade can shield the red light. (If your AKI device is mechanical model ,just make sure tools can down to the center of AKI device)

Click “save” to save the parameter.

So when you want calibrate tool automatic ,the tool will move this point


to start calibrate.




4. Test

Select one tool which one you want calibrate

Click AKI icon



Check positon:

Before first use, select “start test”, then press any direction key, head will move to AKI device, after it done, check the position if it is correct.

If position is good, cancel “start test”


Check sensor:

Select “check photoelectric”

Use something to shield the sensor, if sensor has problem there will has a error.

If sensor is good, cancel “check photoelectric”

5. Start




Press the emergency stop button if anything goes wrong when machine calibrate cutting depth automatic.

Select one tool which one you want calibrate

Click “Execute” to start automatic calibrate. You can get a cutting depth value A.

Click “manual adjust” icon



Use up and down key to calibrate cutting depth manually, get a cutting depth value B.

Calculate $B - A = C$, C is the value which you need set in “repair”

Automatic Knife Initialization

Preset knife: EOT X: 100.0 mm

Present: 38.11 mm Y: 0.0 mm

Alternative felt thickness 0.0 mm Repair: 0.00 mm

Check Photoelectric No Instruction

Start Test Execute

Modify

Exit(E)

If you need cut on the alternative felt, you need set “alternative felt thickness”, this value depend on your actual situation.