

**1. Computer configuration:**


WIN 7, WIN10, WIN11 system

CUP I5,RAM 4G,HDD 250G

**2. Software installation issues:**

Installation is not recommended on computer C disk; may cause software BUG; select WIBU dongle type during installation;

**3. Drive the installation problem:**



WIN10 environment and dog drive to open the cut software;

Please check the file" Software→Download" or enter text in the search engine

**4. Encryption Dog Problems:**

If you need to increase the dog use time, you need to create the dog file and send it to the salesman first;

If you need to add new features, contact the salesman to update the product code.

**5. A software introduction for Cuttersever and Ibrightcut refers to User's Manual;**

**6. Software cannot open:**

Error: unable to find the software copyright license Check the dongle drive; check the dongle connection is normal.

Error72: Check that the computer system time is correct.

XXX.The DLL file is lost, and you will reinstall the software.

**7. Software association issues:**

IBrightCut settings start Cutterserve reselecs the installation directory for CutterSever;

**8. Ports problem:**

The serial port selection prevents the software to connect to the machine; first open the device manager to view the serial port, replace the COM or automatically select; the problem is not solved, please reinstall the software, please contact the technician.

**9. The gas domain does not display the problem:**

Check the serial port;

Check the isolation converter;

Check the 485 board wiring;

Reset the PLC in the gas source box and reopen the software;


Win + R Command Prompt CMD Enter netstat-ano to find the PID of port 8733, and Task

Manager finds the same PID shutdown process to reopen the software;

**10. Computer layout problems cause incomplete software display:**

Set the computer layout to 100%;

**11. Camera was unable to connect to the problem:**



Check the line, model selection, TSW / USB refresh.

**12. The IBrightCut prompt when sending the task, " Direction is beyond the machine width!"**

1. Check that the drawing is out of the blue box range;
2. Check that IBrightCut is correctly associated with CutterServer;
3. Check the bed range setting in the CutterServer P parameters;
4. Please check the array output settings;
5. If the above settings are normal, reopen the file or restart the software.

**13. Data cannot be sent:**

CutterServer Error Report: "PLT file read error"

1. Please check the workspace for data not assigned to any layer;
2. Check that the dashed cut attribute are set for the hardware circle.
3. Please check whether the material thickness and cutting depth are correct.

**14. Parameters cannot be modified:**

After modifying the parameters and saving, close the software and open, and found that the parameter is still the pre-modified value, probably because the directory attribute of the software is set to Read-only. Please cancel the read-only attribute of the software directory and try again.

**15. Shortkey conflict:**

Open the CutterSever Help keymap for a modification.

**16. The TOOL EMPTY appears when the IPIlycut sends the cut file**

Output sets the tool.

17. The IPllycut layer does not display text: TOOL after importing the file, check the Show text.

